



RECOMMENDED ROTOR MAINTENANCE

Clarks rotor thickness is 1.80mm to 1.88mm
To avoid rotor failure, rotors should be replaced when the thickness is worn down to 1.6mm or less, or after 2 years. Whichever comes first.

RECOMMENDED TORQUE SETTINGS

Fitting Position	Fitting Size	Torque Setting
Rotor Bolt	Torx T25	6.2 NM

SERVICE & FITTING VIDEOS

We have an extensive collection of videos, demonstrating all the common service procedures carried out on our brake range.

Please visit
clarks.bike/how-to-videos.html

SERVICE & REPAIR PARTS

We offer an extensive range of spare service and repair parts for all our hydraulic brake systems.

Please visit
clarks.bike/order-spare-parts.html

BOLT TIGHTENING SEQUENCE



www.clarks.bike



CLARKS
EXCEED YOUR LIMITATIONS